## **ISSUE DOCUMENTATION – RTCA SC-186**



Tracking Information (committee secretary only)								
Change Issue Number	11							
Submission Date	13 January 2004							
Status (open/closed/deferred)	Pending							
Last Action Date								

Short Title for	Inconsistency between continuity requirements in Tables 2-3 & 3-1 (& other errors in
Change Issue:	Table 2-3)

Topic:		ASA		High-level		ASAS		STP			ASSAP		CDTI
Document Reference:			DO-289				Originator Information:						
Entire docume	nt (	y/n)	No			N	ame	Jonathan Hammer / Steve Friedman					
Section number	on number(s)			Pł	one	703-883-5209							
Paragraph number(s)				E-r			mail	jhammer@mitre.org					
Table/Figure n	um	ber(s)	Ta	able 2-3 & Ta	ble	3-1	Oı	her	steve@adsi-m4.com				

Pro	posed Rationale for Consideration (originator should check all that apply):
	Item needed to coordinate with other documents
	ASA MASPS
	1090 MHz Link MOPS
	UAT Link MOPS
	TIS-B MASPS
	Previously written CDTI MOPS
	Other (include document title):
	Item needed for harmonization with international requirements
	Item identified during recent ADS-B development activities and operational evaluations
	MOPS clarifications and correction item
	Validation/modification of questioned MOPS requirement item
	Military use provision item
	New requirement item

Nature of Issue:	X	Editorial		Clarity	X	Performance		Functional			
James Description (attack additional about if accessor).											

## <u>Issue Description (attach additional sheets if necessary):</u>

- 1. Table 2-3 says that there is no continuity requirement for CD and ASSA & FAROA, but also says that a TQL of 1 is necessary. TQL 1 requires  $10^{-3}$  continuity.
- 2. The reference in the continuity row of table 2-3 is incorrect and should be to the next section.
- 3. Table 2-3 Row 13 is missing a reference to 2.4.5.3.3.2
- 4. The maximum time to indicate integrity change in 3-1 is across the transmit side and is significantly less than the spec in table 2-3 (which is across tx and rx). However, the large time to indicate integrity change across the receive side does not seem warranted.
- 5. The ASA MASPS should have requirements for time to first ADS-B report to handle the case of the ADS-B rebooting in mid-air. (While A1-C1 is inop, the ADS-B would simply report "no known position" and trust ground multilateration. A requirement for STP reboot might also be useful.)

## Originator's proposed resolution if any (attach additional sheets if necessary):

1. State continuity requirement of 10<sup>-3</sup> for CD and ASSA & FAROA, with a note that explains this is for consistency with other requirements.

- 2. Correct section reference.
- 3. Put in reference to 2.4.5.3.3.2
- 4. Recheck requirements
- 5. Discuss

Issue # 11 Page 2